



## INFORMATIONAL BULLETIN

### *PARTS & SERVICE DEPARTMENT*

300 Maddox Simpson Pkwy  
Lebanon, Tennessee 37090  
615-889-8900 Fax: 615-547-1003  
www.Lochinvar.com

*Date:* 8/22/05

*Bulletin Number:* 2005-18I

---

**TO:** Manufacturers' Representatives, District Sales Managers, Regional Managers, Technical & Customer Service Personnel, Service Agents and Sales & Marketing Personnel

**SUBJECT:** No Shield Hot Service Igniters

---

There will be a product upgrade instituted involving the hot surface igniter used on the TurboCharger. The upgraded hot surface igniter will be manufactured without the protective shield and the lead wires will use a Teflon coating verses the previous shellac coating. These upgrades have been introduced to enhance the longevity of igniters installed in less than optimum conditions.

The upgraded igniter will be used in production on September 1, 2005 (serial number BJ). The part number for the upgraded igniter will remain PLT1151. Stock inventories of the current style igniter will be depleted prior to the upgraded igniter being shipped as a service part.

Should you have any questions please feel free to call the Technical Service at 1-800-722-2101