



## TECHNICAL SERVICE BULLETIN

### *PARTS & SERVICE DEPARTMENT*

300 Maddox Simpson Pkwy  
Lebanon, Tennessee 37090  
615-889-8900 Fax: 615-547-1003  
www.Lochinvar.com

*Date:* 11/11/04

*Bulletin Number:* 2004-21T (revised)

**TO:** Manufacturers' Representatives, District Sales Managers, Regional Managers, Technical & Customer Service Personnel, Service Agents and Sales & Marketing Personnel

**SUBJECT:** Information on programmed parts for the Intelli-Fin

When placing an order for a RLY3027, RLY3026, RLY3023, RLY2717, SMP3000 – SMP3005, & SMP3008 – SMP3014 we need to have the following information:

Sequencer serial # \_\_\_\_\_ (If equipped)

Unit serial # \_\_\_\_\_

Original PO # \_\_\_\_\_

Are changes from the original settings required? If so, what?

\_\_\_\_\_

Which device needs to be programmed? \_\_\_\_\_

If this system is using a building management system then we will also need the domain number, subnet number, and node numbers. \_\_\_\_\_

The parts above need to be programmed from the factory in order for these parts to work correctly.