



TECHNICAL SERVICE BULLETIN

PARTS & SERVICE DEPARTMENT

300 Maddox Simpson Pkwy
Lebanon, Tennessee 37090
615-889-8900 Fax: 615-547-1003
www.Lochinvar.com

Date: 8/29/11 [*REDISTRIBUTE*]

Bulletin Number: 2011-07 T

TO: Manufacturers' Representatives, District Sales Managers, Regional Managers, Technical & Customer Service Personnel, Service Agents and Sales & Marketing Personnel

SUBJECT: Flood Damaged Boilers, Water Heaters, or Pool Heaters

The recent flooding experienced in many areas of the country has caused water damage to many existing boilers, water heaters and pool heaters. The possible damage to a flooded unit can be extensive and present numerous safety hazards. Considering the many problems that will exist with a flooded unit, there is only one reasonable, economical and safe course of action to be followed:

IN THE INTEREST OF PUBLIC HEALTH AND SAFETY, ANY BOILER, WATER HEATER OR POOL HEATER THAT HAS BEEN SUBJECTED TO FLOODING MUST BE REPLACED.

Damage may not be readily visible or immediately detectible, however over a period of time flooded equipment will create dangerous conditions which could result in death, bodily harm or property damage.

Call your qualified contractor to replace your flooded boiler, water heater or pool heater.

Should you have any questions, please contact Technical Service toll free at 800-722-2101.